

In re Patent of: Examiner: S. Hsieh HIROFUMI HIRANO, et al. Group Art Unit: 2861 Appl. No.: 10/052,383 Filed: January 23, 2002 For: INK TAN, INK-JET CARTRIDGE, INK-SUPPLYING APPARATUS, Certificate INK-JET PRINTING APPARATUS AND METHOD FOR SUPPLYING INK OCT 1 2 2004 of Correction U.S. Patent No.: 6,755,500 B September 30, 2004 Issued: June 29, 2004

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

10/04/2004 EAREGAY1 00000060 6755500

01 FC:1811

100.00 DP

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentees

Edward A. Kmett

Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

Facsimile: (212) 218-2200

CA_MAIN 86852v1

CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500BZ

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 66, "Laying-open" should read -- Laid-open--.

COLUMN 3

Line 2, "connected" should read --connected to--;

Line 62, "rectangular," should read --rectangle, --; and

Line 63, "rectangular" should read --rectangle,--.

COLUMN 4

Line 61, "objet" should read --object--.

COLUMN 6

Line 58, "inkjet" should read --ink-jet--.

COLUMN 11

Line 61, "2M" should read --2OM,--.

COLUMN 12

Line 9, "independent" should read – independent of--.

COLUMN 13

Line 4, "bug" should read --bung--; and

Line 9, "2 le" should read --21e--.

COLUMN 15

Line 18, "311" should read --31i--;

Line 31, "6n" should read --on--; and

Line 38, "311." should read --31i.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,755,500 B2

No. of add'l. copies @ 30¢ per page

<u>क्वर्</u> >

9CT 1 3 2004

CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 B2_

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 13, "automatically" should read --automatic--; and

Line 44, "rotate" should read --rotations--.

COLUMN 18

Line 64, "form" should read --from--.

COLUMN 19

Line 19, "formed" should read --formed by--;

Line 21, "communicates" should read --communicates with--; and

Line 57, "simple." should read --simply--.

COLUMN 20

Line 21, "varyingly" should read --varied--; and

Line 27, "varyingly" should read --varied--.

COLUMN 21

Line 18, "detect" should read --detects--; and

Line 45, "form" should read --from--.

COLUMN 22

Line 33, "fifth" should read --sixth--; and

COLUMN 25

Line 6, "shown" should read --shown in--.

COLUMN 26

Line 11, "s" should read --is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. 6,755,500 \$ 2

No. of add'l. copies

@ 30¢ per page

OCT 1 3 2004

CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 BZ

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 27

Line 33, "detect" should read --detects--; and

Line 62, "currently" should read --currently in--.

COLUMN 30

Line 26, "synthesis" should read --synthetic--;

Line 38, "tryfluoromethyl" should read --trifluoromethyl--; and

Line 50, "These" should read -- This--.

COLUMN 31

Line 5, "nozzles" should read --nozzle--;

Line 39, "501M, 501M," should read --501M, 501Y,--;

Line 43, "but ink." should read --but not ink.--; and

Line 47, "ale" should read --able--.

COLUMN 33

Line 8, "shown" should read --shown in--;

Line 21, "conditions." should read --condition--;

Line 23, "view" should read --views--; and

Line 41, "a" should read --an--.

COLUMN 34

Line 8, "in" should read --in the--; and

Line 66, "i.e.," should read --(i.e.,--.

COLUMN 35

Line 5, "medium" should read --medium.--; and

Line 13, "but ink." should read --but not ink.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

OCT 1 3 2004

No. of add'l. copies @ 30¢ per page

36.62°

PATENT NO. 6,755,500

Form PTO 1050 (Rev. 3-82) (Form#30)

Here

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 B2

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 36

Line 13, "prevents" should read --prevent--;

Line 49, "configures" should read --configured--; and

Line 61, "filed" should read --filled--.

COLUMN 37

Line 7, "in Figure." should read --in the Figure.--;

Line 29, "fist" should read --first--;

Line 34, "to fitted" should read --to be fitted--;

Line 59, "10g" should read --log--; and

Line 64, "seating" should read -- sealing--.

COLUMN 38

Line 15, "need-like" should read --needle-like--; and Line 64, "twentieth" should read --twenty-first--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. 6,755,500 B 2

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) (Form#30)

OCT 13 2004



CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 B2

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 39

Line 1, "twentieth" should read --twenty-first--;

Line 6, "twentieth" should read --twenty-first--;

Line 14, "twentieth" should read --twenty-first--;

Line 22, "an" should read --a--; and

Line 25, "synthesis" should read --synthetic--.

CA_MAIN 86841v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,755,500 12

No. of add'l. copies @ 30¢ per page

OCT 1 3 2004

Form PTO 1050 (Rev. 3-82) (Form#30)

☞> _

CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 B2

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 66, "Laying-open" should read -- Laid-open--.

COLUMN 3

Line 2, "connected" should read --connected to--;

Line 62, "rectangular," should read --rectangle, --; and

Line 63, "rectangular" should read --rectangle,--.

COLUMN 4

Line 61, "objet" should read -- object--.

COLUMN 6

Line 58, "inkjet" should read --ink-jet--.

COLUMN 11

Line 61, "2M" should read --2OM,--.

COLUMN 12

Line 9, "independent" should read – independent of--.

COLUMN 13

Line 4, "bug" should read --bung--; and

Line 9, "2 le" should read --21e--.

COLUMN 15

Line 18, "311" should read --31i--;

Line 31, "6n" should read --on--; and

Line 38, "311." should read --31i.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,755,500 62

No. of add'l. copies @ 30¢ per page

□□□> _

OCT 13 2004

CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 BZ

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 13, "automatically" should read --automatic--; and

Line 44, "rotate" should read --rotations--.

COLUMN 18

Line 64, "form" should read --from--.

COLUMN 19

Line 19, "formed" should read --formed by--;

Line 21, "communicates" should read --communicates with--; and

Line 57, "simple." should read --simply--.

COLUMN 20

Line 21, "varyingly" should read --varied--; and

Line 27, "varyingly" should read --varied--.

COLUMN 21

Line 18, "detect" should read --detects--; and

Line 45, "form" should read --from--.

COLUMN 22

Line 33, "fifth" should read --sixth--; and

COLUMN 25

Line 6, "shown" should read --shown in--.

COLUMN 26

Line 11, "s" should read --is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,755,500 62

No. of add'l. copies @ 30¢ per page

OCT 13 2004



CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 B2

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 27

Line 33, "detect" should read --detects--; and

Line 62, "currently" should read --currently in--.

COLUMN 30

Line 26, "synthesis" should read --synthetic--;

Line 38, "tryfluoromethyl" should read --trifluoromethyl--; and

Line 50, "These" should read -- This--.

COLUMN 31

Line 5, "nozzles" should read --nozzle--;

Line 39, "501M, 501M," should read --501M, 501Y,--;

Line 43, "but ink." should read --but not ink.--; and

Line 47, "ale" should read --able--.

COLUMN 33

Line 8, "shown" should read --shown in--;

Line 21, "conditions." should read --condition--;

Line 23, "view" should read --views--; and

Line 41, "a" should read --an--.

COLUMN 34

Line 8, "in" should read --in the--; and

Line 66, "i.e.," should read --(i.e.,--.

COLUMN 35

Line 5, "medium" should read --medium.--; and

Line 13, "but ink." should read --but not ink.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

OCT 1 3 2004

PATENT NO. 6,755,500 62

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) (Form#30)

CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 BZ

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 36

Line 13, "prevents" should read --prevent--;

Line 49, "configures" should read --configured--; and

Line 61, "filed" should read --filled--.

COLUMN 37

Line 7, "in Figure." should read --in the Figure.--;

Line 29, "fist" should read --first--;

Line 34, "to fitted" should read --to be fitted--;

Line 59, "10g" should read --log--; and

Line 64, "seating" should read -- sealing--.

COLUMN 38

Line 15, "need-like" should read --needle-like--; and Line 64, "twentieth" should read --twenty-first--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

OCT 1 3 2004

No. of add'l. copies @ 30¢ per page

PATENT NO. 6,755,500 12

Form PTO 1050 (Rev. 3-82) (Form#30)

CERTIFICATE OF CORRECTION

PATENT NO.

6,755,500 B2

DATED

June 29, 2004

INVENTOR(S) :

Hirano et al.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 39

Line 1, "twentieth" should read --twenty-first--;

Line 6, "twentieth" should read --twenty-first--;

Line 14, "twentieth" should read --twenty-first--;

Line 22, "an" should read --a--; and

Line 25, "synthesis" should read --synthetic--.

CA MAIN 86841v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,755,500B2

No. of add'l. copies @ 30¢ per page

OCT 1 3 2004

Form PTO 1050 (Rev. 3-82) (Form#30)